

From: Noelito Biscocho
Sent: Wednesday, May 27, 2015 9:12 AM
To: William Rhotenberry (EPA-SP)
Cc: Mike McAteer (Mcateer.mike@epa.gov); Steven Cowan; START3
Subject: Ector Drum: HazCat Results table

Good morning Bill.

Please see attached Ector Drum HazCat Results Table for your Action Memo. I also prepared a location map that is associated with this table. It's an unofficial map, using Google Earth, just so you know where the locations are with Column A on the Excel table.

If you have any questions, please feel free to call/email. Have a great day!

Noel Biscocho

1323 Columbia Drive, Suite 307
Richardson, TX 75081
Office: 214.575.3344, ext. 306
Cell: 703.899.0374
Fax: 214.575.4433



Scientific Minds. Common Sense Solutions.
www.css-dynamac.com

This e-mail, and any attachments to it, contain privileged and confidential information intended only for the use of the individual(s) or entity named on the e-mail. If the reader of this e-mail is not the intended recipient, or the employee or agent responsible for delivering it to the intended recipient, you are hereby notified that reading it is strictly prohibited. If you received this e-mail in error, please immediately return it to the sender and delete it from your system. Thank you.

HazCat	GPS*		Location	Content Description	Radiation (mR/hr)	VOC (ppm)	Benzene	Flamability	pH	Oxidizer	Fluoride	Petroleum Product	Iodine, Bromine, Chlorine
HazCat - A	31.886278	-102.293695	Tote East section of property	Golden Brown, Viscous; approx., 3/4 full	0.1	50	NC	No	5 to 6	P	NP	P	NP
HazCat - B	31.886056	-102.293705	Drum area in southeast corner of property	Light golden brown, Not viscous; full	0	55	NC	Yes	7	NP	NP	NP	NP
HazCat - C	31.886083	-102.294658	Tote in West section of property; adjacent to a shipping container	Golden Brown, Viscous; 3/4 full	0.2	102	0	Yes	3 to 4	NP	NP	P	NP
HazCat - D	31.885863	-102.294546	Drum Area South of secondary containment. Drum is in the West end of the drum pad, North of the empty acetone tote.	Brown liquid, No layer; full	0.2	117	0	No	12 to 13	NP	NP	P	NP
HazCat - E	31.885893	-102.294493	Drum Area South of secondary containment. Drum is in the North end of the drum pad	Orange/Brown liquid, Not Viscous; full	0.2	110	0	No	11 to 12	NP	NP	P	NP
HazCat - F (Sample ED-WL 10)	31.88577	-102.294263	Open drum inside the south warehouse	Reddish orange; two layers (liquid and sludge); tested liquid layer; 1/2 full	0	Normal	0	No	3 to 4	NP	NP	NP	NP
HazCat - G	31.885829	-102.294374	On ground surface under shipping container, SW of property between the secondary containment (sample location ED-WL 09) and Open Troft (sample location ED-WL 08)	Waste Oil-like substance	0	Normal	0	No	5 to 6	NC	NC	NC	NC
HazCat - H (Sample ED-WL 08)	31.885865	-102.294254	In open trough, south section of property	Brown liquid; 1/4 full	0	Normal	0	No	12 to 13	NC	NC	NC	NC
HazCat - I (Sample ED-WL 09)	31.885914	-102.294418	In secondary containment area, southwest of property	Brown liquid; 2 inches of liquid, 1 to 2 feet of sludge	0	Normal	0	No	12 to 13	NC	NC	NC	NC

Legend:

P = Present

NP = Not Present

NC = measurement not collected

* = See Attached Map

Hazardous by RCRA definition



Google earth
EPA/START-3 CSS-Dynamac
HazCat® Sample Locations
May 20, 2015

feet
meters



Ector Drum Site

2504 N. Marco Ave., Ector County,
Odessa, TX, 79765